

Product Name	plastic / wood / metal	personal / sharable	twist / flex / bend / mold / squeeze	small / medium / large	snoozy / intriguing	silent / quiet / louder	\$ / \$\$ / \$\$\$	1-5 scale; 5 most durable	featherweight / standard	ho hum / cool / wow!	PASS / FAIL
	4 Pdwuldo	5 Xvhu	6 Prwlrq	7 Vl}h	8 H h0Fdqg	9 Vrxqg	: Frvw	; Gxudelolw	< Zhljkw	43 Ixq Idfwru	44 Vdqlwl}dwlrq whvw
Dqjoh Wzlvw Sx}}	metal	share	twist	medium	intriguing	silent	\$	1	featherweight	Wow!	PASS
Ehdfk lq d E1	sand	personal	mold	medium	intriguing	silent	\$\$	3	standard	cool	FAIL
Ehgghh} Ilggo	plastic/wire	share	bend	medium	snoozy	silent	\$\$	5	standard	ho hum	PASS
Exqfklhv	plastic	share	form	medium	snoozy	quiet	\$\$	4	featherweight	cool	N/A
Fkhhvh) Plfh Ilgg	rubber/latex	personal	squeeze	medium	intriguing	silent	\$\$	2	standard	Wow!	PASS (w talc powder)
Froruixo Vrfn Prqnh Ehggde	plastic/wire	share	bend	medium	snoozy	silent	\$	5	standard	ho hum	PASS
Eudlq Sxwv	putty	personal	mold	small	snoozy	silent	\$\$	4	standard	Wow!	FAIL
Ilggo0lq	plastic	share	rotate	small	snoozy	silent	\$\$\$	5	standard	cool	PASS
Ilgjhw Vslqqh	plastic / metal	share	spin	medium	intriguing	louder	\$\$	5	standard	Wow!	N/A
Ilqjhu Wrs Ed	plastic	share	spin	small	snoozy	quiet	\$\$	5	featherweight	cool	N/A
Ioh{lEor{ Ilgç	wood	share	flex	medium	snoozy	silent	\$\$	5	standard	cool	FAIL
Jhr Wzlvwhu Ilgg	plastic / elastic	share	flex	large	snoozy	silent	\$\$	3	standard	cool	PASS (altered)
Jolwwhu Zdqg/ od	plastic	share	turn	large	intriguing	silent	\$\$\$	5	standard	cool	PASS
Jolwwhu Zdqg/ vp	plastic	share	turn	medium	intriguing	silent	\$\$	5	standard	ho hum	FAIL
J urel	plastic	share	spin	large	intriguing	quiet	\$\$	5	featherweight	Wow!	PASS
Lqilqlw Fx	plastic	share	flex	medium	snoozy	silent	\$\$	5	standard	cool	PASS
Lqilqlw Ol	plastic	share	flex	large	snoozy	silent	\$\$\$	5	standard	cool	PASS
LvrIoh{ Ilgg	rubber / sand	share	squeeze	medium	snoozy	silent	\$\$	5	standard	cool	PASS
Mholnx Pl	plastic	share	flex	medium	snoozy	silent	\$	3	featherweight	cool	PASS
nrrvk	rubber	share	feel	medium	snoozy	silent	\$\$\$	5	standard	cool	PASS (w drying time)
Orrshh}	plastic	share	rotate	medium	snoozy	silent	\$\$	5	standard	cool	PASS
Orrshh} Mu	plastic	share	rotate	small	snoozy	silent	\$\$	5	standard	cool	PASS
Pdjlf Iroglqj Fxeh		share	rotate	medium	snoozy	silent	\$\$	2	standard	cool	FAIL
Phqwd0 Eorfn Ilgç	wood	share	form	medium	snoozy	silent	\$\$	5	standard	cool	FAIL
Plql Phwdo Vsulqj Ilç	metal	share	stretch	medium	snoozy	silent	\$	3	standard	cool	PASS
Slsh Fohdqhuv +832ed	metal	share	form	large	intriguing	silent	\$	3	standard	ho hum	PASS
Sxiihu Ed	latex	personal	squeeze	large	snoozy	silent	\$	2	featherweight	ho hum	PASS (w talc powder)
Udlqerz Pdjq10Vwrqh	metal	share	form	small	snoozy	louder	\$\$	5	standard	cool	PASS
Udlqerz Phwdo Vsulç	metal	share	stretch	small	snoozy	quiet	\$\$	3	standard	cool	PASS
Vqds) Folfn Ilgç	plastic	share	flex	medium	snoozy	louder	\$	5	standard	cool	PASS
Vwuhwfk dqg Erxqfh Ilgç	latex	personal	stretch	medium	snoozy	silent	\$	3	standard	cool	N/A
Vwuhwfk Vwul	rubber/latex	personal	stretch	medium	snoozy	silent	\$	3	standard	cool	PASS (w talc powder)
VzljRv	plastic	share	rotate	medium	snoozy	silent	\$\$\$	5	standard	Wow!	PASS
Wdqjoh Ilggç	plastic	share	twist	medium	snoozy	silent	\$\$	5	standard	cool	PASS
Wdqjoh Uhod{ Wkhud:	plastic	share	twist	large	snoozy	silent	\$\$\$	5	standard	cool	PASS
Wkhuds Ehdg Edç	latex	personal	squeeze	medium	snoozy	silent	\$\$	3	standard	cool	PASS (altered)
Zkdw*]lw ilgjhw	wood	share	form	large	snoozy	silent	\$\$	5	standard	cool	FAIL